

# Globtelecom 2000 S.L.

Address: Av. Ramón y Cajal, 2 P4 F, 29640 Fuengirola, Málaga. Spain



Tel: +34 951 560 502 Fax: 0086 755 2645 6659

Website: www.globtelecom.es

E-mail: info@globtelecom.com



## Quotation for Dinstar E1 T1 gateway

Item	Picture	Part No.	Description
1		MTG200	1*E1,support Echo,G.711 G.723 G.729 ILBC
2			2*E1,support Echo,G.711 G.723 G.729 ILBC
3			4*E1,support Echo,G.711 G.723 G.729 ILBC
5			SS7 OR R2
6			
7	2 E1/T1, 2*100Base- Tx,1*Console port, 1U SIP, <b>PRI</b>		
8		MTG1000-1E1	1 E1/T1, 2*100Base- Tx,1*Console port, 1U chassis, Support SIP/H.323, SS7/PRI
9		MTG1000-2E1	2 E1/T1, 2*100Base- Tx,1*Console port, 1U chassis, Support SIP/H.323, SS7/PRI
10		MTG1000-4E1	4 E1/T1, 2*100Base- Tx,1*Console port, 1U chassis, Support SIP/H.323, SS7/PRI
11		MTG1000-8E1	8 E1/T1, 2*100Base- Tx,1*Console port, 1U chassis, Support SIP/H.323, SS7/PRI

## Globtelecom 2000 S.L.

Address: Av. Ramón y Cajal, 2 P4 F, 29640 Fuengirola, Málaga. Spain

Tel: +34 951 560 502 Fax: 0086 755 2645 6659



Website: www.globtelecom.es

E-mail: info@globtelecom.com

**GLQB**  
telecom

**DINSTAR**

### Quotation for Dinstar E1 T1 gateway

12		MTG2000-20E1	20* E1/T1, 1U SIP,PRI/SS7/R2 G.711,G.729,G.723,Ilbc	
13		MTG3000-63E1	63* E1/T1, 1U SIP, PRI/SS7/R2 G.711A/U,G.723.1,G.729A/B, iLBC, AMR SDH STM-1 155M (63E1)	

#### Remark:

1. No limit for M.O.Q, to be discussed for OEM/ODM projects.
2. Delivery terms: EXW ShenZhen
3. Delivery time: 3 days upon order confirmed
4. Payment Terms: 30% Deposit before project start and T/T in advance for balance.
- 5.
6. Validity of this quotation: 3 weeks
7. Warranty period: 12 months

## Globtelecom 2000 S.L.

Address: Av. Ramón y Cajal, 2 P4 F, 29640 Fuengirola, Málaga. Spain

Tel: +34 951 560 502 Fax: 0086 755 2645 6659





Website: www.globtelecom.es

E-mail: info@globtelecom.com

**GLQB**  
telecom

**DINSTAR**

### Quotation for Dinstar Enterprise GSM gateway

Item	Picture	Part No.	Description	
1		DWG2000E-4G-B	·SIP/MGCP ·4*GSM Channels ·Quad-band 850/900/1800/1900 MHz ·G.711.G.723.1.G.729A, suport 723+729 both. ·IMEI ·Support SIM Bank	
2		DWG2000E-8G-B	·8*GSM	
3		DWG2000F-16G-B	·SIP/MGCP ·16*GSM Channels ·Quad-band 850/900/1800/1900 MHz ·G.711.G.723.1.G.729A, suport 723+729 both. ·IMEI ·Support SIM Bank	
4		DWG2000G-32G-B	·SIP/MGCP ·MCU+8*GSM Channels ·IMEI ·Support SIM Bank /SERVER	

#### Remark:

1. No limit for M.O.Q, to be discussed for OEM/ODM projects.
2. Delivery terms: EXW ShenZhen
3. Delivery time: 3 days upon order confirmed
4. Payment Terms: 30% Deposit before project start and T/T in advance for balance.
- 5.
6. Validity of this quotation: 3 weeks
7. Warranty period: 12 months

# Globtelecom 2000 S.L.

Address: Av. Ramón y Cajal, 2 P4 F, 29640 Fuengirola, Málaga. Spain

Tel: +34 951 560 502 Fax: 0086 755 2645 6659

Website: www.globtelecom.es

E-mail: info@globtelecom.com

**GLQB**  
telecom

**DINSTAR**

## Quotation for Dinstar FXS FXO gateway

Item	Picture	Part No.	Description	
1		DAG1000-4S	<ul style="list-style-type: none"><li>-SIP/MGCP</li><li>-4*FXS, T.38 FAX</li><li>-G.711,G723.1,G.729 A/B</li><li>-PPPoE, DHCP Client/Server</li><li>-G.168 Echo Cancellation</li><li>-VAD,CNG, PLC and Dynamic Jitter Buffer</li></ul>	
2		DAG1000-4O	<ul style="list-style-type: none"><li>-SIP/MGCP</li><li>-4*FXO,T.38 FAX</li><li>-G.711.G.723.1.G.729A</li><li>-WEB. telnet configuration</li><li>-PPP/PPPOE,DHCP Client/Server</li><li>-VAD,CNG, PLC and Dynamic Jitter Buffer</li></ul>	
3		DAG1000-8S	<ul style="list-style-type: none"><li>-SIP/MGCP</li><li>-8*FXS, T.38 FAX</li><li>-G.711,G723.1,G.729 A/B</li><li>-TR069/SNMP</li><li>-IPV6</li><li>-IMS</li></ul>	
4		DAG1000-8O	<ul style="list-style-type: none"><li>-SIP/MGCP</li><li>-8*FXO, T.38 FAX</li><li>-G.711.G.723.1.G.729A</li><li>-WEB. telnet configuration</li><li>-PPP/PPPOE,DHCP Client/Server</li><li>-VAD,CNG, PLC and Dynamic Jitter Buffer</li></ul>	
5		DAG1000-4S4O	<ul style="list-style-type: none"><li>-SIP/MGCP</li><li>-4*FXS+4*FXO,T.38 FAX</li><li>-G.711.G.723.1.G.730A</li><li>-WEB. telnet configuration</li><li>-PPP/PPPOE,DHCP Client/Server</li><li>-VAD,CNG, PLC and Dynamic Jitter Buffer</li></ul>	
6		DAG2000-16S	<ul style="list-style-type: none"><li>-SIP/MGCP</li><li>-16*FXS, T.38 FAX</li><li>-G.711,G723.1,G.729 A/B</li><li>-TR069/SNMP</li><li>-IPV6</li><li>-IMS</li></ul>	
7		DAG2000-16O	<ul style="list-style-type: none"><li>-SIP/MGCP</li><li>-16*FXO,T.38 FAX</li><li>-G.711.G.723.1.G.729A</li><li>-WEB. telnet configuration</li><li>-PPP/PPPOE,DHCP Client/Server</li><li>-VAD,CNG, PLC and Dynamic Jitter Buffer</li></ul>	
8		DAG2000-8S8O	<ul style="list-style-type: none"><li>-SIP/MGCP</li><li>-8*FXS+8*FXO, T.38 FAX</li><li>-G.711.G.723.1.G.729A</li><li>-WEB. telnet configuration</li><li>-PPP/PPPOE,DHCP Client/Server</li><li>-VAD,CNG, PLC and Dynamic Jitter Buffer</li></ul>	

# Globtelecom 2000 S.L.

Address: Av. Ramón y Cajal, 2 P4 F, 29640 Fuengirola, Málaga. Spain

Tel: +34 951 560 502 Fax: 0086 755 2645 6659

Website: www.globtelecom.es

E-mail: info@globtelecom.com

**GLQB**  
telecom

**DINSTAR**

## Quotation for Dinstar FXS FXO gateway

9		DAG2000-24S	·SIP/MGCP ·24*FXS, T.38 FAX ·G.711,G723.1,G.729 A/B ·TR069/SNMP ·IPV6 ·IMS	
10		DAG2000-32S	·SIP/MGCP ·32*FXS, T.38 FAX ·G.711,G723.1,G.729 A/B ·TR069/SNMP ·IPV6 ·IMS	
11		DAG2500-48S	·SIP/MGCP ·48*FXS, T.38 FAX ·G.711,G723.1,G.729 A/B ·TR069/SNMP ·IPV6 ·IMS	
12		DAG2500-64S	·SIP/MGCP ·64*FXS, T.38 FAX ·G.711,G723.1,G.729 A/B ·TR069/SNMP ·IPV6 ·IMS	
13		DAG2500-72S	·SIP/MGCP ·72*FXS, T.38 FAX ·G.711,G723.1,G.729 A/B ·TR069/SNMP ·IPV6 ·IMS	
14		DAG3000-112S	·SIP/MGCP ·112*FXS, T.38 FAX ·G.711,G723.1,G.729 A/B ·TR069/SNMP ·IPV6 ·IMS	

### Remark:

1. No limit for M.O.Q, to be discussed for OEM/ODM projects.
2. Delivery terms: EXW ShenZhen
3. Delivery time: 1 days upon order confirmed
4. Payment Terms: 30% Deposit before project start and T/T in advance for balance.
- 5.
6. Validity of this quotation: 3 weeks
7. Warranty period: 12 months

# Globtelecom 2000 S.L.

Address: Av. Ramón y Cajal, 2 P4 F, 29640 Fuengirola, Málaga. Spain

Tel: +34 951 560 502 Fax: 0086 755 2645 6659

Website: www.globtelecom.es

E-mail: info@globtelecom.com

**GLOB**  
telecom

**DINSTAR**

## Quotation for Dinstar GSM gateway

Item	Picture	Part No.	Description	
1		DWG2000-1G	<ul style="list-style-type: none"><li>·SIP/MGCP</li><li>·1 GSM Channels</li><li>·Quad-band</li><li>850/900/1800/1900 MHz</li><li>·G.711.G.723.1.G.729A</li><li>·IMEI</li></ul>	
2		DWG2000E-4G	<ul style="list-style-type: none"><li>·SIP/MGCP</li><li>·4*GSM Channels</li><li>·Quad-band</li><li>850/900/1800/1900 MHz</li><li>·G.711.G.723.1.G.729A,</li><li>support 723+729 both.</li><li>·IMEI</li><li>·Support SIM Bank</li></ul>	
3		DWG2000E-4G-M	4GSM+Antenna Combiner inside	
4		DWG2000E-8G	8*GSM	
5		DWG2000E-8G-M	8*GSM+Antenna Combiner inside	
6		DWG2000F-16G	<ul style="list-style-type: none"><li>·SIP/MGCP</li><li>·16*GSM Channels</li><li>·Quad-band</li><li>850/900/1800/1900 MHz</li><li>·G.711.G.723.1.G.729A,</li><li>support 723+729 both.</li><li>·IMEI</li><li>·Support SIM Bank</li></ul>	
7		DWG2000F-16G-M	16*GSM+Anterna Comber inside	

## Globtelecom 2000 S.L.

Address: Av. Ramón y Cajal, 2 P4 F, 29640 Fuengirola, Málaga. Spain

Tel: +34 951 560 502 Fax: 0086 755 2645 6659



Website: www.globtelecom.es

E-mail: info@globtelecom.com

**GLOB**  
telecom

**DINSTAR**

### Quotation for Dinstar GSM gateway

8		DWG2000G-32G	·SIP/MGCP ·MCU+8*GSM Channels ·IMEI ·Support SIM Bank /SERVER	
9		DWG2000G-32G-M	32*GSM+Antena Comber inside	

#### Remark:

1. No limit for M.O.Q, to be discussed for OEM/ODM projects.
2. Delivery terms: EXW ShenZhen
3. Delivery time: 3 days upon order confirmed
4. Payment Terms: 30% Deposit before project start and T/T in advance for balance.
- 5.
6. Validity of this quotation: 3 weeks
7. Warranty period: 12 months